

Residential Construction Home Remodeling Cost **Estimates**



The estimates reflected in this guide are based upon national average ariations in costs include regional differences, upgraded materials, job exity, disposal fees, and labor costs¹. Please of east 3 licensed/professional contractors prior to final selection.

Landscaping/Porch/Deck/Patio/Fence

Landscaping

o	
→ lay soil & sod	\$1-\$/sq.ft
add fill dirt/regrade at foundation	\$500+
add/regrade swale for drainage	\$400-\$800/side
→ sprinkler system	\$1,000
termite prevention (chemical soil treatment)	\$500-\$1,300
Porch	

o	
▶ flooring	\$15-\$25/lin.ft
railing	\$15-\$45/lin.ft
▶ skirting	\$15/lin.ft
> steps-concrete	\$400
> steps-wood	\$250
replace support post	\$75-\$125

replace wood stairs

concrete (stamped)

concrete - repair

flagstone/fieldstone

•	
Deck	
custom designed & built	\$30-\$50/sq.ft
 pressure treated 	\$10-\$25/sq.ft
→ composite	\$15-\$50/sq.ft
→ cedar	\$25-\$50/sq.ft
→ railing	\$10-\$35/lin.ft
→ steps	\$55-\$110/lin.ft
 replace support post 	\$75-\$125
replace wood stairs	\$250-\$500
Patio	

Interlock brick/stone	\$8-\$10/sq.
patio stone	\$5-\$10/sq.
ence	
· chain link (4 ft.)	\$10/lin.
• wood-cedar (5 ft.)	\$15-\$20/lin.
wood-pressure treated (5 ft.)	\$10-\$15/lin.
reset post in concrete	\$60/pos

Garage/Driveway/Walkway

Gai age	
 detached carport 	\$4,000+
 detached wood frame-single 	\$8,000+
 detached wood frame-double 	\$13,000+
 detached block-single 	\$18,000+
 detached block-double 	\$24,000+
 removal of existing garage 	\$1,500+
Overhead Doors	

Overhead Doors	
 automatic garage door opener 	\$300+
 cladboard-single 	\$450-\$650
 cladboard-double 	\$750-\$1000
metal-single (one-piece)	\$700
metal-double (one-piece)	\$1,100

Overhead Doors, cont'd

wood-single (sectional)

interlock brick/stone

 wood-double (sectional) 	\$1,250
Driveway	
 asphalt paving (new base) 	\$5-\$15/sq.ft
asphalt paving (resurface)	\$4-\$7 /sq.ft
asphalt (seal)	\$2-\$4 /sq.ft
concrete (stamped)	\$5-\$15/sq.ft
· concrete - repair	\$3-\$7/sq.ft

\$725

\$15-\$20/sq.ft

\$10-\$20/sq.ft drainage at bottom of driveway \$5-\$15/lin.ft repoint masonry

Walkway

concrete - new	\$5-\$15/sq.ft
concrete - repair	\$3-\$6/sq.ft
→ mud jack	\$600+

Structure/Exterior/Basement

\$400	Structure	
\$250	 addition (foundation to roof) 	\$1,200-\$1,500
\$75-\$125	 excavation/waterproofing 	\$1,300-\$1,500
\$250-\$500	 foundation cracks (excavation method) 	\$300-\$600
φ230-φ300	 foundation cracks (injection method) 	\$1,500-\$2,500
#20 #F0/ #	masonry work (labor, rebar, etc.)	\$10-\$15/sq.ft
\$30-\$50/sq.ft	lintel (masonry wall)	\$4,500-\$6,000
\$10-\$25/sq.ft	rebuild chimney	\$65-\$125/lin.ft
\$15-\$50/sq.ft	 underpin/align masonry chimney 	\$2,500-\$3,500
\$25-\$50/sq.ft	 install metal chimney cap 	\$1,200-\$1,500
\$10-\$35/lin.ft	 wood rot repair 	\$6-\$12/lin.ft
\$55-\$110/lin.ft	paint siding	\$1\$2/sq.ft
\$75-\$125 \$250-\$500	re-caulk siding/windows	\$.50-\$1/lin.ft
\$230-\$300	 retaining wall-concrete 	\$65-200/sq.ft
#10 #15/ C	retaining wall-wood	\$25-150/sq.ft
\$10-\$15/sq.ft	 retaining wall-concrete 	\$65-200/sq.ft
\$3-\$5/sq.ft	retaining wall-wood	\$25-150/sq.ft
\$15-\$25/sq.ft	Exterior	
\$8-\$10/sq.ft	aluminum siding	\$3-\$7/sq.ft
\$5-\$10/sq.ft	 brick veneer 	\$6-\$12/sq.ft
#10/P	brick cleaning (unpainted)	\$2-\$4/sq.ft
\$10/lin.ft	brick cleaning (painted)	\$3-\$5/sq.ft

 brick repointing \$3-\$6/sq.ft brick rebuild \$8-\$15/sq.ft cedar/hardboard siding \$4-\$8/sq.ft stucco \$6-\$8/sq.ft skim top coat (stucco/EIFS) \$3-\$6/sq.ft repair stucco/EIFS \$8-\$15/sq.ft caulk windows/door (stucco/EIFS) \$3-\$6/sq.ft caulk breach locations (stucco/EIFS) \$10-\$15 ea. seal exposed wall bottom (stucco/EIFS) \$5-\$6/lin.ft.

\$35-\$50/lin.ft window drain pan (stucco/EIFS) \$65-\$115/lin.ft window lintel flashing (stucco/EIFS) \$12-\$15/lin.ft door lintel flashing (stucco/EIFS) \$15-\$25/lin.ft remove/replace substrate/framing (stucco/EIFS) \$35-\$55/sq.ft repair cracks/delamination (stucco/EIFS) \$105-\$120 ea.

\$200-\$300 ea.

 repair holes/minor damage (stucco/EIFS) \$35-\$40 ea general caulking (stucco/EIFS) \$3-\$5/lin.ft

kickout flashings (stucco/EIFS)

deck flashing (stucco/EIFS)

Exterior, cont'd		Flat Roofs		Windows, cont'd	
→ backer rod & caulk (stucco/EIFS)	\$5-\$6/lin.ft	roll roofing asphalt (90 lb.)	\$1.50-\$3.00/sq.ft	replace double pane (glass)	\$75-\$150 ea.
vinyl siding	\$3-\$7/sq.ft	• 4-ply (tar and gravel)	\$3.50-\$5.50/sq.ft	replace ropes/springs	\$50-\$100 ea.
→ steel siding	\$3-\$7/sq.ft		\$10-\$15/sq.ft	, , , ,	\$50-\$150 ea.
add/replace storm window	\$50-\$150		\$3.00-\$5.00/sq.ft		\$25-\$75 ea.
hinged door	\$450-\$700	Ö		Ceilings/Walls	, , , , , , , , , , , , , , , , , , , ,
double door	\$650-\$950		\$1100 \$2.007.0q.10	remove wall (non-load bearing)	\$50-\$100/lin.ft
 hinged with side lites 	\$1,250-\$2,500		\$2.5-\$3.5/sq.ft	• drop tile ceiling	\$2.70-\$6.00/sq.ft
sliding door	\$850-\$1,500	0	\$2.5-\$5.5/\$q.it	replace drop ceiling tiles	\$.50-\$2.00/sq.ft
atrium door	\$950-\$1,850		\$4-\$9/lin.ft	• acoustic ceiling (suspended)	\$2.00-\$4.00/sq.ft
• french doors	\$1,100-\$2,500		\$3-\$6/lin.ft	drywall (new)	\$1.50-\$4.00/sq.ft
aluminum storm door	\$150-\$500	9	\$15-\$30/lin.ft	drywall over plaster	\$1.30-\$4.00/sq.ft
metal insulated door	\$100-\$200		\$100-\$200	• plaster (new)	\$2.00/sq.ft \$2.50-\$5.00/sq.ft
metal basement doors	\$550-\$1,250	. 6	\$8-\$13/lin.ft	plaster (new)plaster (over existing plaster)	•
patio door replace	1,500-\$2,00	O			\$2.50/sq.ft
patio door-replace patio door-brick wall (6 ft.)	\$300-\$400		\$2-\$6/lin.ft	repair drywall/plaster	\$2.50-\$5.00/sq.ft
patio door-wood wall (6 ft.)			\$10.00-\$25.00 ea.	stucco/stipple	\$1.00/sq.ft
door hardware	\$50-\$200	Flashing/Venting	****	walls (insulation, drywall)	\$2.50-\$6.00/sq.ft
door nardwaredoor repair	\$25-\$150	chilling hashing (sloped asphale)	\$200-\$400	walls painting (3 coats)	\$1.25/sq.ft
Basement	φ25-φ150	ciminity mashing (national ap)	\$300-\$500	• wallpaper	\$1.00-\$4.00/sq.ft
basement entrance	\$1,500-\$1,800	• metal cricket at chimney	\$200-\$400	wood trim	\$1.00-\$5.00/lin.ft
basement main beam	\$1,500-\$1,800	parapet wall flashing	\$25/lin.ft	paint walls & trim	\$.25-\$1.00/sq.ft
		→ roof vent	\$35-\$85 ea.	insulation	\$.75-\$2.00/sq.ft
basement support post/foundation	\$150-\$250	→ ridge vent	\$5-10/lin.ft	texture ceiling (no prep)	\$100+\$2.00/sq.ft
labor to set postlower basement	\$15-\$25/lin.ft	→ soffit vent	\$35-\$65 ea.		
	\$1,200-\$1,500	→ skylight	\$350-\$800	• carpet-clean	\$35-\$50/room
• underpin corner of structure	\$1,100-\$1,600	ice/water shield	\$1-\$3/lin.ft	carpet-outdoor	\$1.50/sq.ft
• underpin/replace foundation	\$550-\$950/lin.ft	→ valley flashing	\$15-\$25/lin.ft	carpet & underpad	\$3.00-\$6.50/sq.ft
install sump pump	\$1,500+ea.	roof/wall flashing	\$3-\$6/lin.ft	ceramic tile	\$5.00-\$20.00/sq.ft
• mud jack concrete slab	\$600+ea.	repair/replace vent flashing	\$100-\$150	hardwood	\$6.00-\$15.00/sq.ft
remove/replace concrete slab	\$10-\$15/sq.ft	repair/replace valley flashing	\$200-\$275	parquet flooring	\$5.00-10.00/sq.ft
repair/replace unit block wall	\$200-\$350/lin.ft	Chimney		hardwood-re-finish	\$1.75-\$4.50/sq.ft
• support pier for 8' concrete block wall	\$415 +еа.	clean & evaluate	\$150-\$300	vinyl-sheet	\$5.00-\$8.50/sq.ft
repair/replace rotted or damaged joists	\$100-\$250	chimney extension	\$100-\$250/lin.ft	→ vinyl-tile	\$2.00-\$8.00/sq.ft
repair/replace rotted or damaged sill plate	\$75-\$100/lin.ft	 chimney repointing 	\$5.00-\$10.00/brick	sub-floor (new)	\$2.00-\$3.00/sq.ft
interior drain tile system	\$65-\$100/lin.ft	 concrete crown (single flue) 	\$100-\$250	Doors	
• exterior drain tile system	\$80-\$105/lin.ft	 concrete crown (double flue) 	\$200-\$350	bi-fold-louver	\$800
realign foundation wall	\$80-\$125/lin.ft	rain cap	\$75	bi-fold-panel	\$600
install helical tie-back	\$750-\$850 ea	re-lin flue (stainless steel)	\$30-\$40/lin.ft	 hollow-core slab 	\$75-\$150
Roof System		Interior		 hollow-core panel 	\$100-\$250
Sloped Roofs				custom with casing/hardware	\$400
asphalt shingle (over existing)	\$1.00-\$1.75/sq.ft	Windows		 solid-core single hinged 	\$250-\$400
asphalt shingle (strip & re-shingle)	\$1.75-\$3.00/sq.ft	→ vinyl	\$200-\$400 ea.	interior-panel	\$400
• asphalt shingle (strip a re-shingle) • asphalt shingle (premium)	3.00-\$5.00/sq.ft	→ aluminum	\$150-\$300 ea.	→ french	\$400-\$850
cedar shake/shingle	\$3.00-\$5.50/sq.ft	• wood	\$300-\$500 ea.	sliding glass	\$1750
replace ridge shingles on wood roof	\$6.00-\$10.00/lin.ft	→ awning	\$45/sq.ft	→ closet	\$150-\$350
spot maintenance wood roof	\$350-\$950	awning/casement (replace)	\$40/sq.ft	 door hardware 	\$45-\$75
clay tile	\$5.50-\$7.50/sq.ft	→ bay/bow	\$35-\$40/sq.ft	 → door repair 	\$15-\$75
ciay the concrete tile	\$5.50-\$8.50/sq.ft	• casement	\$50/sq.ft	Stairs/Railings	
slate/tile	\$5.00-\$9.00/sq.ft	→ garden	\$800-\$1200 ea.	· curved stairs-oak (7 risers)	\$7,000+
repair slate/tile	\$50-\$90 ea.	double hung	\$40/sq.ft	→ spiral stair-oak	\$4,700
plastic shingle	\$3.50-\$5.50/sq.ft	double hung (replace)	\$35/sq.ft	standard stair (7 risers)	\$50-\$100/lin.ft
• metal (standing seam)	\$2.50-\$7.00/sq.ft	→ skylight	\$250-\$800 ea.	→ stair railing	\$15-\$50/lin.ft
complete tear-off (per layer)	\$25-\$50/sq.ft	→ slider-aluminum	\$25/sq.ft	 wood stairs repair 	\$5-\$50/lin.ft
steep roof (>9:12)	\$50-\$100/sq.ft	slider-aluminum (replace)	\$20/sq.ft	 pull-down attic stairs 	\$350-\$850
soffit (replace)	\$3-\$5/lin.ft	storm-aluminum	\$45-\$175 ea.	Insulation	•
rake-fascia (replace)	\$15-\$25/lin.ft	• thermal glass (existing frame)	\$25/sq.ft	rigid exterior (prior to finish)	\$0.75-\$1.25/sq.ft
ranc-iascia (i cpiace)	Ψ1.3-Ψ2.3/1111.10	baseboard/door/window casing	\$2.50/lin.ft	R20-batt (walls)	\$0.60-\$1.50/sq.ft
		replace single pane (glass)	\$25-\$75 ea.	· · · · · · · · · · · · · · · · · · ·	,

Insulation, cont'd		Bathroom		Upgrade, cont'd	
R20-loose (walls)	\$0.50-\$0.75/sq.ft	tub surround-ceramic tile	\$10-\$30/sq.ft	replace main entrance cable	\$500-\$750
R32-batt (attic)	\$1.50-\$2.00/sq.ft	tub enclosure-plastic	\$300-\$400	run underground conductors	\$5-\$10/lin.fr
R32-loose (attic)	\$0.75-\$1.50/sq.ft	tub surround-fiberglass	\$250-\$675	replace underground conductors with romex	\$3.50-\$6.50/sq.fr
→ wall/roof cavity	\$1.50-\$3.00/sq.ft	tub/shower enclosure-fiberglass repair	\$150-\$400	add additional receptacle or replace	\$90-\$130
→ R20 in crawlspace/garage ceiling	\$1.50-\$2.75/sq.ft	• glass doors	\$150-\$600	replace ungrounded outlet with grounded	\$45-\$100
Fireplaces	¥ ¥ = q	cast iron bathtub	\$200-\$600	aluminum wiring connectors	\$.50-\$1.00/sq.f
direct vent fireplace	\$2,000-\$4,000	tub/shower fixture	\$250-\$1,100	upgrade to CO/ALR outlet or switch	\$75 min.+\$30-\$50 ea
• metal flue insert	\$75-\$150/lin.ft	→ whirlpool bath/faucet	\$2,000-\$4,000	• junction box	\$25-\$50
masonry fireplace	\$200-\$400/lin.ft	• exhaust fan	\$150-\$300	• junction box cover	\$3-\$5
clay flue		Security System		breaker panel-main	\$400-\$600
· damper	\$225-\$650	• alarm monitoring	\$20-\$35/mo.	breaker panel-auxilliary	\$500-\$750
glass doors	\$200-\$550	• alarm system	\$0-\$2,500	110v circuit breaker(replace)	\$50-\$100
firebrick rebuild	\$500-\$1,500	intercom system (retrofit)	\$1,200	220v circuit breaker(replace)	\$75-\$125
firebrick repoint	\$150-\$500	• wired system	\$0-\$1,300	add bonding strap at water main	\$50-\$100
• gas insert	\$2,500-\$3,500	• wireless motion detectors	\$500	add bonding strap at meter base	\$25-\$75
gas insert		Miscellaneous Interior	Ψ300	 knob & tube wiring (replace) 	\$6,000-\$12,000
hearth extension	\$250	central vacuum (retrofit)	\$1,200-\$3,000	Heating/Cooling	
flue cleaning	\$100	central vacuum (retront) central vacuum (canister only)	\$1,200-\$3,000 \$1,000 \$2,000	ricating, cooming	_
• metal box insert	\$700-\$2,500		φ1,000-φ2,000	Forced Air System	
masonry (with flue rough-in)	\$6,000+	Electrical		 annual clean & service - furnace or boiler 	\$75-\$200
• wood stove	\$1,500-\$2,500	Retrofit		· clean duct	\$150-\$300
Kitchen	Ψ1,500 Ψ2,500	• attic fan	\$350-\$550	→ air duct (new)	\$10-\$15/lin.ft
• wall cabinets	\$80-\$1750/lin.ft	baseboard heater (4')	\$150-\$230	air duct (retrofit)	\$15-\$21/lin.f
base cabinets		ceiling fan	\$150-\$350	blower/motor	\$150-\$300
refinish/reface cabinets	\$200-\$550/lin.ft	doorbell system	\$80-\$200	 replace fan switch 	\$75-\$150
	\$70-\$160/lin.ft \$60-\$200/lin.ft	doorbeil system dryer duct	\$100-\$150	repair/replace gas burner	\$100-\$350 ea
counter-granitecounter-slate		hard-wired smoke detectors	\$75-\$150 ea.	 replace gas valve 	\$150-\$250
	0-\$150/lin.ft	 battery powered smoke detectors 	\$50-\$100 ea.	 replace thermocouple 	\$750-\$150
counter-marble	\$60-\$130/lin.ft	exhaust fan-bathroom	\$135-\$150	convert oil to gas (1 story)	\$2,000-\$3,000
• counter-limestone	\$85-\$125/lin.ft	• vent hood-oven	\$200-\$250	convert hot water to forced air (I story)	\$6,000+
• counter-Corian	\$60-\$110/lin.ft	• exterior light fixture	\$100-\$250	electronic air filter	\$400-\$700
counter-engineered stone	\$50-\$85/lin.ft	fluorescent light fixture	\$150-\$250	▶ gas-mid efficiency	\$1,500-\$2,800
• counter-butcher block	\$50-\$75/lin.ft	ridorescent light fixture represent light fixture represent light fixture	\$75-\$100	▶ gas-high efficiency	\$2,700-\$3,500
counter-concrete	\$50-\$75/lin.ft	pround-private system (with ground rods)	\$200-\$300	humidifier-drum type	\$75-\$150
• counter-laminate	\$25-\$50/lin.ft	receptacle-conventional		 humidifier-flow through type 	\$350-\$450
counter-ceramic/porcelain	\$10-\$25/lin.ft	•	\$100-\$150	metal line existing chimney flue	\$500-\$1,000
• sink-porcelain	\$650-\$820	receptacle-split	\$150-\$250	Hot water system	
sink-stainless steel	\$550-\$730	receptacle-exterior with cover	\$15U-\$25U	circulating pump	\$150-\$300
sink fixture	\$250-\$850	receptacle/breaker-replace conventional wit		cast iron radiator	\$450-\$650
replace sink trap	\$65-\$100	receptacle-CO/ALR (aluminum)	\$75 min.+\$30-\$50 ea.	• expansion tank	\$250-\$300
kitchen renovation	\$50-\$200/sq.ft	receptacle-stove/dryer	\$75-\$100	oil boiler-standard	\$2,500-\$4,200
• dishwasher	\$550-\$890	receptacle-rewire reverse polarity	\$50 min.+\$10 ea.	→ gas boiler-standard	\$2,500-\$3,500
• garbage disposer	\$175-\$300	basic light and switch (new)	\$150-\$350 ea.	gas boiler-high efficiency	\$3,500-\$5,000
range hood	\$300-\$500	repair/replace fixture	\$75-\$150 ea.	reline oil boiler firebox	\$150-\$350 ea
Bathroom		repair/replace switch or outlet	\$50-\$75 ea.	install oil burner	\$350-\$550 ea
→ bathroom renovation	\$50-\$175/sq.ft	• exterior spotlights	\$150-\$350 ea.	install above ground oil tank	\$650-\$1,100 ea
→ add I/2 basement bath	\$1,500+	security system	\$500-\$750	removal of oil tank	\$350-\$500
→ add 3/4 basement bath	\$2,500+	phone or cable jack	\$25-\$50 ea.	radiator/boiler removal	\$1,500-\$2,000
▶ basin-pedestal	\$300-\$1,500	Upgrade		install thermostat	\$150-\$650 ea
vanity and sink basin	\$250-\$1,500	rewire home and upgrade panel	\$3-\$5/sq.ft	baseboard heaters	\$150-\$350 ea
bathtub-replace & retile	\$1,500+	I00-Amp (new panel)	\$1,000-\$1,500	electric baseboard heaters	\$15-\$25/lin.ft
→ shower-replace & retile	\$1,500+	I 00-Amp (existing panel)	\$500-\$800	radiator	\$300-\$600
→ shower stall-plastic	\$700-\$1,900	200-Amp (new panel)	\$1,800-\$2,000	radiator zone valve	\$75-\$150
shower stall-ceramic tile	\$2,000-\$3,700	200-Amp (existing panel)	\$1,000-\$1,200	asbestos removal from ducts/flue/pipes	\$20-\$30/lin.ft
retile tub/shower	\$700-\$2,000	120/240 volt circuit	\$200-\$500	Air Condition or/Host Deves	φ20-φ30/III.II
replace damaged ceramic tile	\$10-\$30/sq.ft	 replace service entrance cable 	\$500-\$750	Air Conditioner/Heat Pump	A100 607
regrout ceramic tile	\$5-\$10/sq.ft	replace meter base	\$250-\$500	annual clean & service - a/c or heat pump	\$100-\$275
→ shower stall-fiberglass	\$400-\$900	repair loose meter base	\$50-\$150	· clean evaporator/condenser coils	\$75-\$200

Air Conditioner/Heat Pump, cont'd	
→ air handler 3-ton (vertical)	\$1,200-\$1,500
air handler 3-ton (horizontal)	\$1,500-\$1,800
→ central A/C-existing duct	\$1,500-\$3,000
central A/C-attic mounted, separate duct	\$7,500-\$9,000
heat recovery ventilator (HRV)	\$1,500-\$2,500
→ heat pump	\$4,500-\$6,000
condensor unit	\$1,100-\$3,000
• evaporator & condensor units	\$2,500-\$6,000
compressor - heat pump or a/c	\$800-\$1,500
condenser fan	\$225-\$450
air handler drip pan	\$150-\$350

Plumbing

			-1	_
U	pg	ra	a	е

J pgrade	
hose bibb	\$80-\$150
hot water tank (40.gal-electric)	\$400-\$500
replace electric heating element/thermostat	\$100-\$150
hot water tank (30 galgas)	\$300-\$400
hot water tank (40 galgas)	\$400-\$500
hot water tank (50 galgas)	\$500-\$800
dispose of old unit	+\$50-\$75 ea.
replace gas valve/burner	\$125-\$150
replace T&P relief valve	\$50-\$100
 add drip tube to T&P relief valve 	\$35-\$75
· add drip pan beneath	\$150-\$500
main water service	\$100-\$200/lin.ft
main shut-off valve	\$150-\$400
supply lines -cpvc	\$5-\$10/lin.ft
supply lines -copper	\$10-\$15/lin.ft
supply lines -pvc	\$5-\$10/lin.ft
insulate supply lines	\$1-\$3/lin.ft
main waste drain line	\$25-\$75/lin.ft
 snake drain line 	\$75-\$200
waste drain line - cast iron	\$10-\$20/lin.ft

water softener

dryer vent pipe

laundry tub/connection

septic system - add/replace

individual shut-off valve to fixture

· drain pan under washing machine

٠.,٠	a vene pipe	φ5 φ15/
→ sum	p pump (install)	\$150-\$250
replace/extend natural gas lines		\$25-\$35/lin.ft
Bathro	om	
→ serv	ice call	\$75-\$130
→ shov	wer connection	\$200
→ toile	t-flush mechanism	\$100-\$150
→ toile	t-replace	\$150-\$500
→ toile	t hardware	\$45-\$100
→ toile	et wax seal	\$45-\$125
→ toile	t-replace seal	\$150-\$250
→ toile	t-unclog	\$100-\$200
→ sink	faucet	\$75-\$175
→ sink	trap	\$65-\$175
→ sink	stopper	\$50-\$100
→ tub	stopper	\$150-\$400
• corr	ect hot/cold reversal at fixture	\$120-\$280
rivate	Plumbing System	

Private Plumbing, System, cont'd

\$25-\$50

\$800-\$1500

\$300-\$500

\$150-\$500

\$5-\$15/lin.ft

\$8,000-\$15,000

Appliances	
 well-pressure tank 	\$350-\$800
well water lines	\$5-\$10/lin.ft
well-suction/jet pump	\$500-\$900
 well-submersible pump 	\$800-\$1,000
→ well-deep	\$35-\$45/lin.ft
well-shallow	\$20-\$25/lin.ft
 sewage waste pump 	\$1,300-\$1,700
laundry tub & waste pump	\$250-\$350
 septic tank cleaning 	\$150-\$300
▶ leeching field - repair	\$1,200-\$2,500
→ septic tank (1,000 gal.)	\$1,700-\$3,000
rivate Fluiribilig, System, Cont d	

window a/c unit	\$375-\$800
→ stove	\$450-\$1,700
 replace stove heating elements 	\$450-\$1,700
replace stove gasket	\$100-\$125
→ cooktop	\$300-\$1,300
 replace stove/ooktop burners 	\$70-\$105
→ wall oven	\$850-\$2,000
dishwasher	\$40-\$1,000
 replace dishwasher gasket 	\$100-\$150
garbage disposal	\$150-\$500
trash compactor	\$350-\$700
range hood	\$150-\$600
 built-in microwave 	\$350-\$1,100
 replace refrigerator gasket 	\$125-\$175



Steve Rodriguez

Owner & Professional Home Inspector

11813 W. 148th St.

Olathe, Ks. 66062

Office: 913.685.3364 Cell: 816.564.3081

Email: steve@bulldoginspect.com Web: www.BulldogInspect.com

Life Expectancies

Component	Avg. Life (yrs)
Roof Covering	
 standard asphalt shingles 	12-15
 premium asphalt shingles 	15-30
→ wood shingle	10-25
· concrete/clay tile	30-50
→ asbestos cement	40-80
→ slate tile	30-80
→ roll roofing	5-15
→ tar & gravel	15-25
→ metal	60
Heating	
forced air furnace	10-25
→ heat pump	10-15
→ oil tank	40
 water/steam boiler-welde 	d steel 15-30
 water/steam boiler-cast iron 	
 water/steam circulating pun 	np 10-25
Cooling	
· central air	10-15
condenser compressor	8-17
window unit	10-20
Plumbing	
→ galvanized water supply pipe	e 20-35
· copper water suply pipe	55-75
 plastic water supply pipe 	55-75
hot water heater	5-15
→ septic/sewer pump	5-10
→ well pump	10
Appliances	
• dishwasher	5-12
→ dryer	5-15
garbage disposal	5-12
oven/range	15-20
 washing machine 	5-15

